

Legend

● Site Location

0 450 900 1,800 Feet



Prepared for:
U.S. EPA Region 8



Contract No.:

TDD:
0003/1307-12

DCN:
W0049.1A.00081





Prepared By:
Weston Solutions, Inc.
START IV

Suite 100
1435 Garrison Street
Lakewood, CO 80215

FIGURE 1
SITE LOCATION MAP
FORMER GUEST HOUSE
YANKTON SIOUX
TRIBE PROPERTIES
MARTY, SOUTH DAKOTA

Date: 11/18/2013



Prepared for:
 U.S. EPA Region 8

Contract No.:

TDD:
 0003/1307-12

DCN:
 W0049.1A.00081



Prepared By:
 Weston Solutions, Inc.
 START IV


Suite 100
 1435 Garrison Street
 Lakewood, CO 80215



FIGURE 2
SITE VICINITY MAP
FORMER GUEST HOUSE
YANKTON SIOUX
TRIBE PROPERTIES
MARTY, SOUTH DAKOTA

Date: 11/18/2013

St. Katherine's, Marty Indian School (Floor Plan) and Sample Locations
 1989 Asbestos Inspection and 2013 TBA Phase II Inspection



Components with ACM > 1% highlighted in yellow (2013 and 1989 sampling)


Emergency Lights and Exit Signs (lithium batteries)

Light Fixtures (fluorescent light bulbs)

No Soil samples – surrounded by concrete sidewalks

Figure 3. Floor Plan and Sampling Locations (1st Floor)

St. Katherine's, Marty Indian School (Floor Plan) and Sample Locations
1989 Asbestos Inspection and 2013 TBA Phase II Inspection



Components containing >1% ACM highlighted in yellow (2013 and 1989 samples)
Emergency Lights and Exit Signs (lithium batteries)
Light Fixtures (ballasts/fluorescent bulbs)

Figure 4. Floor Plan and Sampling Locations (2nd Floor)

St. Katherine's, Martyr Indian School (Floor Plan) and Sample Locations
 1989 Asbestos Inspection and 2013 TBA Phase II Inspection




Figure 5. Floor Plan and Sampling Locations (Basement)

St. Katherine's, Marty Indian School (Floor Plan) and Sample Locations
1989 Asbestos Inspection and 2013 TBA Phase II Inspection

Components containing >1% ACM highlighted in yellow




Figure 6. Floor Plan and Sampling Locations (Roof)