

2/24/2021 AI# 3106
Livermore Industrial Plating

by Scott, Curtis (EEC)



CCS, 2/24/2021, AI# 3106, Livermore Industrial Plating: The dip tank previously observed to contain plating solution has been emptied and the contents containerized. This particular dip tank was staged under a hole in the room and had minimal free board when previously observed. Arrow marks the location of dip tank during previous visits (and inspections) when it was located under the compromised roof.



CCS, 2/24/2021, AI# 3106, Livermore Industrial Plating: The dip tank previously observed to contain plating solution has been emptied and the contents containerized. This particular dip tank was staged under a hole in the room and had minimal free board when previously observed.



CCS, 2/24/2021, AI# 3106, Livermore Industrial Plating: The dip tank previously observed to contain plating solution has been emptied and the contents containerized. This particular dip tank was staged under a hole in the room and had minimal free board when previously observed. These are 16 drums that contain the plating solution previously held in the dip tank.



CCS, 2/24/2021, AI# 3106, Livermore Industrial Plating: Other dip tanks still contain plating solution. But they are currently staged away from water intrusion points in the roof.