U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT Greenville Truck - Removal Polrep Initial and Final Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region IV

Subject: POLREP #1

Initial/Final Greenville Truck

E15445

Greenville, MS

Latitude: 33.3701010 Longitude: -91.0760000

To:

From: Chuck Berry, OSC

Date: 8/25/2015

Reporting Period: 08/17/2015 - 08/20/2015

1. Introduction

1.1 Background

Site Number: V4AS Contract Number:
D.O. Number: Action Memo Date:

 Response Authority: OPA
 Response Type:
 Emergency

 Response Lead:
 PRP
 Incident Category:
 Removal Action

NPL Status: Non NPL Operable Unit:

 Mobilization Date:
 8/17/2015
 Start Date:
 8/17/2015

 Demob Date:
 8/20/2015
 Completion Date:
 8/20/2015

CERCLIS ID: RCRIS ID:

ERNS No.: State Notification:

FPN#: E15445 Reimbursable Account #:

1.1.1 Incident Category

Clean Water Act (CWA) and Oil Pollution Act (OPA) Emergency Response

1.1.2 Site Description

A tanker truck full of biodiesel rolled off the highway and spilled approximately 3,300 gallons of product into a low-lying wetland area, a headwater of Steele Bayou.

1.1.2.1 Location

Approximately 1 mile south of Highway 1 on US Highway 82 in Greenville, Mississippi, at the intersection of Highway 82 and Lillie Drive.

1.1.2.2 Description of Threat

There is a release of oil into navigable waters of the US as defined by OPA and CWA.

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

2.1.2 Response Actions to Date

Around 1330 hours on August 17, a tanker truck carrying biodiesel fuel rolled over on Highway 82 southwest of downtown Greenville, MS. The truck released into the drainage ditch approximately 3,200 gallons of biodiesel, roughly half of the total load. The flow then traveled over ground until it entered a slough, the headwaters of Steele Bayou. Steele Bayou empties into the Yazoo River, which is a tributary of the Mississippi River. Steele Bayou is a "water of the US" under CWA and OPA. Based on the volume released, both the EPA and the Mississippi Department of Environmental Quality launched emergency responders. The responsible party was allegedly involved in an altercation with the responding emergency services, and was either asked to leave or left the scene of his own volition. As a result, no response was undertaken by the RP to recover the fuel from the truck or the slough. Based on this lack of response, MDEQ initiated a response by hiring USES. Based on conversations with MDEQ subsequent to that, OSC Berry offered to provide a Pollution Removal Funding Authorization (PRFA) to MDEQ to pay for the response. The scope of work was set to remove the remaining fuel from the tanker, upright the tanker, contain migrating fuel, remove fuel from waterways, and address impacted soils that threaten to further impact waterways.

MDEQ contracted with USES to respond to the site. The Greenville Fire Department was already on scene and dammed up the drainage ditch with sand, but only after a large amount of product escaped from the vehicle. The fuel ran south down the drainage ditch and entered a small slough or wetland area. USES used an excavator to build a containment dam at the slough's outfall, effectively containing most of the product in the slough. The slough is about 0.25 acres and had about 1--2 feet of water in places. The pond is full of biota: frogs, crawfish, tadpoles, small minnows, carp, and several large grinnel, or bowfin fish, a least one of which was almost three feet long. No dead biota was observed during the response.

USES drilled holes in all five compartments of the tanker truck, and a towing company righted and removed the vehicle. Just over 3,200 gallons of biodiesel was recovered from the truck and placed into temporary storage tanks brought to site by USES. OSC Berry arrived on site at this point, about 2330 hours Monday night. Operations proceeded throughout the night. USES began using vacuum trucks to remove water and fuel from the pond. A total of 15,000 gallons of water was collected by mid day Tuesday, and the pond was effectively drained. USES tried to remove as much vegetative debris from the pond area as possible, but the volume and muddy conditions made work slow. Meanwhile, USES used an excavator to remove the oil-impacted sod from the wreck area. Only the top surface was scraped, as there were fiber optic cables, a water main, and a natural gas main running through the drainage ditch. The risk of damage to these utilities was not worth the benefit of removing the impacted soil.

The trucking company representative returned to the site Tuesday morning and contacted his insurance company which dispatched a representative. A Unified Command meeting was held in which the RP, MDEQ, and EPA agreed to the workplan and the RP's insurance company agreed to cover all the response costs from the initiation of activities Monday afternoon. The PRFA to MDEQ was subsequently cancelled. A planning meeting was held to discuss future operations and deliverables, including an Operation and Maintenance (O&M) Plan.

Over Tuesday night until Wednesday morning, the pond filled through ground seepage. An estimated 1,500 gallons of oily water was removed by USES. The biodiesel greatly emulsified with the water, rendering it cloudy with oily droplets on the surface. It was apparent that the fuel was soaking into the mud and releasing when the water rose. Flow in this pond is slow, as it is at the headwaters of the Steele bayou drainage system. UC decided to attempt one flushing action with help from the FD. This proved difficult and time-consuming with little net effect on the aggregation of oil in the pond after 11,000 gallons of water was added to the system. Discussions with MDEQ and the RP led to the decision that natural attenuation and biodegradation may be the best treatment method. Biodiesel degrades in weeks instead of months like petroleum diesel. The containment dam was converted to an underflow dam, and the O&M plan was executed. USES will monitor the site under the supervision of MDEQ.

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

The truck was owned and operated by:

Kenneth Jones Jones Liquid Transport 4382 US Highway 61 Merigold, MS 38759 (662) 721-0211

The insurance company is:

Energi Insurance 10 Centennial Drive Suite 201 Peabody, MA 01960 ATTN Timothy Butler 978-531-1822, ext. 7738

2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Manifest #	Treatment	Disposal
Oil-impacted Water	Water	15,000 gal			
Oil-impacted debris and soil	Soil/debris	2 cuy			

2.2 Planning Section

2.2.1 Anticipated Activities

2.2.1.1 Planned Response Activities

No further EPA activity is anticipated for this response. The RP, through its contractor USES, will implement the O&M plan with oversight by MDEQ.

2.2.1.2 Next Steps

Once MDEQ agrees the removal action is complete, the underflow dam will be removed and the site returned to its natural state.

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

3.1 Unified Command

EPA

MDEQ Washington County EMA Jones Liquid Transport

3.2 Cooperating Agencies

Greenville Police and Fire Energi Insurance Company

4. Personnel On Site

No information available at this time.

5. Definition of Terms

No information available at this time.

6. Additional sources of information

No information available at this time.

7. Situational Reference Materials

No information available at this time.