

### Legend

- Air Monitoring Location
- Fence Line
- Work Zone
- Chipping Area
- 1 Foot Excavation (a)
- Stockpile
- Area of Additional Assessment and / or Excavation


### Gamma Activity (cpm)

- 0 - 34,712
- 34,713 - 40,447
- 40,448 - 59,695
- > 59,695

Gamma Activity (cpm)	Correlated Ra-226 Concentration (pCi/g)
0 - 34,712	0 - 2.0
34,713 - 40,447	2.1 - 5
40,448 - 59,695	5 - 15
> 59,695	> 15

### ABBREVIATIONS

cpm counts per minute  
 pCi/g picocuries per gram  
 Ra-226 Radium-226



## Transfer Station 2

### Post 2012 Remediation Surface Gamma Activity

Cove, Apache County, Arizona



(a) Surface gamma activity post excavation October and November 2012.