



#### Legend

- No exceedance of EPA ecological screening levels (As/Se),
- EPA ecological screening level exceedance (As/Se), ash content ≤ 10%
- EPA ecological screening level exceedance (As/Se), ash content > 10%
- ⊗ Not sampled
- ★ Approximate Spill Location

#### Notes:

- RED indicates an exceedance of EPA ecological screening levels.
- EPA ecological screening value for As 9.8 mg/kg.
- EPA ecological screening value for Se 2.0 mg/kg.
- All sample locations are FWS-SF11-L-## where ## is the number listed in the label.
- 00 is the location of sample FWS-SF11

Imagery Source:  
ESRI, USGS Mapping Service, 2013

Eden Coal Ash Spill  
Eden, North Carolina

FWS-SF11 Delineation  
Analytical Results Map  
July 1, 2014

