


#### Legend

- No exceedances for EPA ecological screening levels (As, Se)
- EPA ecological screening level exceedance (Se), ash content ≤1%
- EPA ecological screening level exceedance (Se), ash content >1%

Notes:  
Post-Dredge sediment samples - collected at the 0-6" layer for metals. Splits of those samples were sent for percent ash if there was an exceedance of EPA ecological screening levels

RED indicates an exceedance of EPA ecological screening levels.

Imagery Source:  
ESRI, Mapping Service, 2013



Eden Coal Ash Spill  
Eden, North Carolina

Schoolfield Dredge Area  
Post-Dredge  
Assessment Results Map  
(May 22 - June 12, 2014)

