

Legend


- No exceedances for EPA ecological screening levels (As, Se)
- EPA ecological screening level exceedance (Se), ash content ≤1%
- EPA ecological screening level exceedance (Se), ash content >1%

Notes:
¹Visual suspect ash in the 6"-12" layer at this location warranted sampling of the 12"-16" layer

RED indicates an exceedance of EPA ecological screening levels.

S = sample collected at visible shore line.

Imagery Source:
 ESRI, Mapping Service, 2013



Eden Coal Ash Spill
 Eden, North Carolina

Schoolfield Dredge Area
 Re-assessment Results Map

