

#### Legend


- No exceedances for EPA ecological screening levels (As, Se)
- EPA ecological screening level exceedance (Se). ash content <=1%
- EPA ecological screening level exceedance (Se), ash content >1%

#### Notes:

Post-Removal composite surface soil samples were collected for metals analysis.

RED indicates an exceedance of EPA ecological screening levels.

Imagery Source:  
ESRI, USGS Mapping Service, 2013



Eden Coal Ash Spill  
Eden, North Carolina

Town Creek  
Post-Removal  
Assessment Results Map  
June 30, 2014



Sample Location	Sample Depth:	0"-6"		
	Date Collected	Arsenic (mg/kg)	Selenium (mg/kg)	Ash Content
TC-1	6/30/2014	3.3	0.74J	-
TC-2	6/30/2014	3.3	0.75J	-
TC-3	6/30/2014	4.0	0.70	-
TC-4	6/30/2014	3.00	0.72J	-
TC-5	6/30/2014	3.7	0.50J	-
TC-5 DUP	6/30/2014	2.6J	0.43J	-
TC-1	6/30/2014	5.00	0.68J	-