

# **'Plains' at Stevens Facility Release**

## **Daily Situation Report, September 29, 2014 (Day 13)**

### **Safety:**

There were no injuries or incidents. All operations were conducted safely.

### **Operations:**

**UC:** The RP and SOSC will meet onsite at 10:00am CDT on 10/3/2014, end of the Operational period of the IAP, to determine the future response status.

All Divisions – No precipitation was observed in the 24 hour period between 07:00 hours 9/28/2014 to 07:00 hours 9/29/2014.

Division A: O&M activity. Small patch of free product was observed about 110' downgrade SW from the point-of-origin. Oil Gator™ was applied to the area (see the attached photograph log). Will continue to monitor the division daily.

Division B: O&M activity, No free product observed. Will continue to monitor the division daily.

Division C: O&M activity, three patches of free product were observed in the oil “duck bill” vacuum recovery area and Oil Gator™ was applied to the area (see the attached photograph log). Will continue to monitor the division daily.

Air Monitoring: N/A There is no longer any product present to cause exposure to workers.

**Environmental:** If water is present, then water effluent samples being collected downstream of Division C. All activity is devoted to weather surveillance and storm water control, if needed. Sampling will continue through 10/3/2014 provide there is water available to sample. Next rain is forecast for 10/2 (80%) and 10/3/2014 (60%). The RP and SOSC will meet onsite

### **On-site Personnel:**

Plains: 1

CTEH: 0

Complete Environmental: 3

Clarkco: 0

C-K Associates: 0

USCGA (FOSC-R): 0

# **'Plains' at Stevens Facility Release**

**Daily Situation Report, September 29, 2014 (Day 13)**

MDEQ: 0

Bonner Analytical: 1

## **On-site Equipment:**

100' Containment Boom (1000' available <0.5 hours away)

(0) 130 Bbl. Vac Truck

(0) 70 Bbl. Vac Truck

(0) Skim Pack

(0) ATV

(0) Backhoe

(0) Mini Excavator

(0) Frac Tanks

(2) Roll-Off Boxes

(0) Roll-Off Box Truck

(0) Response Trailer

(0) Equipment Trailer

(0) Boom Trailer

(0) UtilityTrailers

(0) UltraRae

(0) ProRae

(0) MultiRae

(0) Gastec

(8) Bags Oil Gator™

(0) Farm tractor with Tiller

## **Recovery Numbers:**

Liquids: 0 – No Activity.

Solids: 0 - No Activity

**Photograph Logs 9/29/2014 by James Welch, Operations Section Chief**



N 31° 59' 22, W 88° 50' 10"



Stain 1-Division A – NW Corner

**Photograph Logs 9/29/2014 by James Welch, Operations Section Chief**



N 31° 59' 16, W 88° 50' 15"



Stain 2-Division C – NW Corner near vacuum truck recovery



**Photograph Logs 9/29/2014 by James Welch, Operations Section Chief**



N 31° 59' 16", W 88° 50' 16"



Stain 3-Division C – NW Corner near west boom

**Photograph Logs 9/29/2014 by James Welch, Operations Section Chief**



N 31° 59' 16", W 88° 50' 15"



Stain 4-Division C – NW Corner near vacuum truck recovery



**Photograph Logs 9/29/2014 by James Welch, Operations Section Chief**



Division C—Looking SW

**Photograph Logs 9/29/2014 by James Welch, Operations Section Chief**



Division C – Looking ESE



**Photograph Logs 9/29/2014 by James Welch, Operations Section Chief**



Division C – Looking W