

'Plains' at Stevens Facility Release

Daily Situation Report, October 02, 2014 (Day 16)

Safety:

There were no injuries or incidents. All operations were conducted safely.

Operations:

UC: The RP and SOSC will meet onsite at 10:00am CDT on 10/3/2014, end of the Operational period of the IAP, to determine the future response status.

All Divisions – 0.2+ inches of precipitation was observed in the rain gauge from the 24 hour period between 07:00 hours 10/01/2014 to 07:00 hours 10/02/2014.

Division A: O&M activity. Fresh well water was observed to be overflowing its tank near the point-of-origin and continuing to flood the NW corner of Division A. No free product observed. Will continue to monitor the division daily.



10-2-2014 Division A – Looking NNW

'Plains' at Stevens Facility Release

Daily Situation Report, October 02, 2014 (Day 16)



10-2-2014 Division A to Division B Transition – Looking SW

Division B: O&M activity. Fresh well water was observed flowing down about 60% of the distance from the top of the hill and down gradient. A large whitetail doe was observed browsing near the Division B to Division C transition zone. A large feral hog (about 250 lbs) was observed rooting in the dry drainage swale about 100 feet north of Division C. No free product observed. Will continue to monitor the division daily.

'Plains' at Stevens Facility Release

Daily Situation Report, October 02, 2014 (Day 16)



10-2-2014 Division B – Hog rooting looking SW

'Plains' at Stevens Facility Release

Daily Situation Report, October 02, 2014 (Day 16)

Division C: O&M activity. No effluent water was observed at the east end near the culverts/boom; therefore, no water grab samples were able to be taken. No free product observed. Will continue to monitor the division daily.



10-2-2014 Division C – Looking W

Air Monitoring: N/A There is no longer any product present to cause exposure to workers.

Environmental: If water is present, then water effluent samples being collected downstream of Division C. All activity continues to be devoted to weather surveillance and storm water control, if needed. Sampling will continue through 10/3/2014 provide there is water available to sample. Next rain is forecast for 10/2 (50%) and 10/3/2014 (80%).

On-site Personnel:

Plains: 1

CTEH: 0

Complete Environmental: 0

Clarkco: 0

'Plains' at Stevens Facility Release

Daily Situation Report, October 02, 2014 (Day 16)

C-K Associates: 0

USCGA (FOSC-R): 0

MDEQ: 0

Bonner Analytical: 1

On-site Equipment:

100' Containment Boom (1000' available <0.5 hours away)

(0) 130 Bbl. Vac Truck

(0) 70 Bbl. Vac Truck

(0) Skim Pack

(0) ATV

(0) Backhoe

(0) Mini Excavator

(0) Frac Tanks

(2) Roll-Off Boxes

(0) Roll-Off Box Truck

(0) Response Trailer

(0) Equipment Trailer

(0) Boom Trailer

(0) Utility Trailers

(0) UltraRae

(0) ProRae

(0) MultiRae

(0) Gastec

(8) Bags Oil Gator™

(0) Farm tractor with Tiller

Recovery Numbers:

Liquids: 0 – No Activity.

'Plains' at Stevens Facility Release

Daily Situation Report, October 02, 2014 (Day 16)

Solids: 0 - No Activity