

Morrow Lake Sediment Release - Photolog

Photos Take By: Dan Capone on 10/19/2020

Submitted Time: 10/20/2020



Photo Number: 1

Photo Direction: East

Photo Location Description: Containment looking upstream from Morrow Dam

Photo Comments:

Morrow Lake Sediment Release - Photolog

Photos Take By: Dan Capone on 10/19/2020

Submitted Time: 10/20/2020



Photo Number: 2

Photo Direction: West

Photo Location Description: Right descending bank containment

Photo Comments: Looking toward dam

Morrow Lake Sediment Release - Photolog

Photos Take By: Dan Capone on 10/19/2020

Submitted Time: 10/20/2020



Photo Number: 3 **Photo Direction:** Northeast

Photo Location Description: RDB containment

Photo Comments: looking upstream

Morrow Lake Sediment Release - Photolog

Photos Take By: Dan Capone on 10/19/2020

Submitted Time: 10/20/2020



Photo Number: 4

Photo Direction: Southeast

Photo Location Description: Bank treatment installed around mid-channel island

Photo Comments:

Morrow Lake Sediment Release - Photolog

Photos Take By: Dan Capone on 10/19/2020

Submitted Time: 10/20/2020



Photo Number: 5

Photo Direction: East

Photo Location Description: Bank treatment on downstream end of mid-channel island

Photo Comments:

Morrow Lake Sediment Release - Photolog

Photos Take By: Dan Capone on 10/19/2020

Submitted Time: 10/20/2020



Photo Number: 6

Photo Direction: East

Photo Location Description: Mid-channel island – partial containment installed

Photo Comments: