

Photographic Documentation
Susie Adit
Rimini, MT
TO:

Photo: 1

Description:

Access road with slight incline leading to Susie portal access.



Photo: 2

Description:

Top of road, surface drain from adit (portal on the right).



Photographic Documentation
Susie Adit
Rimini, MT
TO:

Photo: 3

Description:

Collapsed slope with dirt & debris blocking portal door



Photo: 4

Description:

Photo of side walls with mostly fine dirt making the slope around the portal unstable



Photographic Documentation
Susie Adit
Rimini, MT
TO:

Photo: 5

Description:

Current surface drain from adit leading to lower slope down to the pond.



Photo: 6

Description:

View of lower slope drain leading down to pond



Photographic Documentation
Susie Adit
Rimini, MT
TO:

Photo: 7

Description:

View from above portal access looking down into the collapsed section



Photo: 8

Description:

View from the side above portal access looking down into the collapsed section



Photographic Documentation
Susie Adit
Rimini, MT
TO:

Photo: 9

Description:

Looking down to the
pond from the portal
access



Photo: 10

Description:

Looking down to the
pond from the portal
access



Photographic Documentation
Susie Adit
Rimini, MT
TO:

Photo: 11

Description:

Public road through town and next to the drainage pond. (looking north)



Photo: 12

Description:

Trees and vegetation on the south side of the drainage pond. Pond just to the right of the photo.

