



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No. 1	Date: 12/01/2021	<div data-bbox="699 363 1289 1146" data-label="Image">  </div>
Direction Photo Taken: Southeast		
Description: View of tailrace from well beneath Sitka Sound Science Center building (oil discharge occurred at a crack in the wall of the well).		
Photo No. 2	Date: 12/01/2021	<div data-bbox="699 1167 1289 1948" data-label="Image">  </div>
Direction Photo Taken: North		
Description: Boom and sheen in tailrace northeast of Sitka Sound Science Center building.		

Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
3

Date:
12/01/2021

Direction Photo Taken:

Down/east

Description:

Boom and sheen in tailrace.



Photo No.
4

Date:
12/01/2021

Direction Photo Taken:

Northeast

Description:

View of large and small stormwater drain discharge locations (SW-02 and SW-03).



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
5

Date:
11/30/2021

Direction Photo Taken:

Down/east

Description:

View of small stormwater discharge pipe (SW-03).



Photo No.
6

Date:
12/01/2021

Direction Photo Taken:

Northeast

Description:

View large and small stormwater discharge locations (SW-02 and SW-03).



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
7

Date:
11/30/2021

Direction Photo Taken:

East

Description:

Smaller diameter pipe inside a larger pipe located inside Sitka Sound Science Center building well.



Photo No.
8

Date:
12/02/2021

Direction Photo Taken:

Southwest

Description:

Sitka utility service representatives locating and marking utility service lines in the library parking lot.



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
9

Date:
12/02/2021

Direction Photo Taken:

South

Description:

Contractor excavating Test Pit 1 in library parking lot.



Photo No.
10

Date:
12/02/2021

Direction Photo Taken:

South

Description:

Backfilling Test Pit 1 excavation in library parking lot.



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
11

Date:
12/02/2021

Direction Photo Taken:

Down

Description:

Groundwater seeping into Test Pit 1 in the library parking lot. A light oil sheen is visible on the water surface.



Photo No.
12

Date:
12/02/2021

Direction Photo Taken:

South

Description:

Backfilling Test Pit 1 in the library parking lot.



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
13

Date:
12/02/2021

Direction Photo Taken:

Down

Description:

Water seeping into Test Pit 1 in the library parking lot.



Photo No.
14

Date:
12/02/2021

Direction Photo Taken:

South

Description:

Water seeping into Test Pit 2 in the library parking lot.



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
15

Date:
12/02/2021

Direction Photo Taken:

Down/southeast

Description:

Water sampling at Test Pit 2 in the library parking lot.



Photo No.
16

Date:
12/02/2021

Direction Photo Taken:

Down/southeast

Description:

Water seeping into Test Pit 2 in the library parking lot.



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
17

Date:
12/03/2021

Direction Photo Taken:

East-southeast

Description:

Test Pit 3 excavation in front of library building.



Photo No.
18

Date:
12/03/2021

Direction Photo Taken:

East

Description:

Test Pit 3 excavation.



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
19

Date:
12/03/2021

Direction Photo Taken:

East-northeast

Description:

Backfill Test Pit 3.



Photo No.
20

Date:
12/03/2021

Direction Photo Taken:

South

Description:

Contractor preparing to excavate Test Pit 3, with Sitka Sound Science Center building visible in background (white building).



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
21

Date:
12/03/2021

Direction Photo Taken:

Southwest

Description:

Collecting a water sample from Test Pit 3.



Photo No.
22

Date:
12/03/2021

Direction Photo Taken:

Southwest

Description:

Collecting a water sample from Test Pit 3.



Project Name:
Sitka Sound Science Center Oil Spill

Site Location:
City and Borough of Sitka, Alaska

Task Order No.:
68HE0722F0013

Photo No.
23

Date:
11/30/2021

Direction Photo Taken:

Down

Description:

Map depicting buried utility locations, circa 1955. Note the labeled "oil line" beneath the proposed library building location.

