

Lodge Grass Drums

Photo Log

Description: START personnel performing air monitoring during initial entry.

Category: Site Photo

Latitude: 45.305631

Date Taken: 2/23/2021

Longitude: -107.359759

Tags:



Description: START personnel collecting samples during initial entry.

Category: Site Photo

Latitude: 45.305631

Date Taken: 2/23/2021

Longitude: -107.359759

Tags:



Description: ERRS personnel bulking drum contents following categorization.

Category: Site Photo

Latitude: 45.305631

Date Taken: 2/24/2021

Longitude: -107.359759

Tags:



Description: START sampling unknown drum contents

Category: Site Photo

Latitude: 45.305575

Date Taken: 2/23/2021

Longitude: -107.359527777778

Tags:



Description: ERRS personnel placing shippable drums onto trailer for relocation following categorization.

Category: Site Photo

Latitude: 45.305631

Date Taken: 2/24/2021

Longitude: -107.359759

Tags:



Lodge Grass Drums

Photo Log

Description: ERRS personnel excavating impacted soil in the former vicinity of the drums.

Category: Site Photo Latitude: 45.305631

Date Taken: 3/25/2021 Longitude: -107.359759

Tags:



Description: ERRS personnel transferring impacted soil to cubic yard boxes for disposal following excavation activities.

Category: Site Photo Latitude: 45.305631

Date Taken: 3/25/2021 Longitude: -107.359759

Tags:



Description: ERRS unloading an overpacked drum at the temporary staging area

Category: Site Photo Latitude: 45.7298

Date Taken: 2/24/2021 Longitude: -107.656594444444

Tags:



Description: Temporary staging established until final disposal is arranged.

Category: Site Photo Latitude: 45.7297397

Date Taken: 2/26/2021 Longitude: -107.6564756

Tags:



Description: Excavated soils and drums being loaded for disposal

Category: Site Photo Latitude: 45.7298888888889

Date Taken: 4/27/2021 Longitude: -107.656747222222

Tags: Site File



Lodge Grass Drums

Photo Log

Description: Waste being loaded for disposal

Category: Site Photo

Latitude: 45.7299277777778

Date Taken: 4/27/2021

Longitude: -107.656638888889

Tags: Site File



Description: Waste Truck, loaded and ready for departure

Category: Site Photo

Latitude: 45.7296972222222

Date Taken: 4/27/2021

Longitude: -107.656761111111

Tags: Site File

