



383 Industrial Way, Suite 300  
 Anchorage, AK 99501 (907) 258-8661  
 anchorage@oneatlas.com



Lab Code 200124-0

# PLM BULK SAMPLE ANALYSIS FOR ASBESTOS

Lab Login #: 0230472 Report #: 0230472  
 Atlas Job #: NA Report By: A. Lang  
 Client Project #: 1 Report Date: 02/16/2023

Client: US EPA Collected By: Client  
 222 W. 7th Ave Collection Date: 02/14/2023  
 Anchorage AK 99513 Analyzed By: A. Lang  
 Date Analyzed: 02/16/2023

TAT: 24 Hour Sample Count: 7 Layer Count: 7  
 Project Name/ Location: West 26th Ave Apartments Received By: A. Lang  
 Received Date: 02/15/2023

Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components	(%)	Asbestos Type	(%)
0230472-001 W26-1	Ceiling Popcorn Texture Popcorn Ceiling, White, Homogeneous, Non-Fibrous	LAYER 1 100%	Other Non-Fibrous Material	100%	None Detected	0%
				<b>Total % Non-Asbestos:</b>	100.0%	<b>Total % Asbestos:</b> No Asbestos Detected
0230472-002 W26-2	Ceiling Popcorn Texture Popcorn Ceiling, White, Homogeneous, Fibrous	LAYER 1 100%	Other Non-Fibrous Material	95%	Chrysotile	5%
				<b>Total % Non-Asbestos:</b>	95.0%	<b>Total % Asbestos:</b> 5.0%
0230472-003 W26-3	Ceiling Popcorn Texture Popcorn Ceiling, White, Homogeneous, Fibrous	LAYER 1 100%	Other Non-Fibrous Material	95%	Chrysotile	5%
				<b>Total % Non-Asbestos:</b>	95.0%	<b>Total % Asbestos:</b> 5.0%
0230472-004 W26-4	Ceiling Popcorn Texture Popcorn Ceiling, White, Homogeneous, Fibrous	LAYER 1 100%	Other Non-Fibrous Material	95%	Chrysotile	5%
				<b>Total % Non-Asbestos:</b>	95.0%	<b>Total % Asbestos:</b> 5.0%
0230472-005 W26-5	Ceiling Popcorn Texture Popcorn Ceiling, White, Homogeneous, Fibrous	LAYER 1 100%	Other Non-Fibrous Material	95%	Chrysotile	5%
				<b>Total % Non-Asbestos:</b>	95.0%	<b>Total % Asbestos:</b> 5.0%
0230472-006 W26-6	Ceiling Popcorn Texture Popcorn Ceiling, White, Homogeneous, Fibrous	LAYER 1 100%	Other Non-Fibrous Material	95%	Chrysotile	5%
				<b>Total % Non-Asbestos:</b>	95.0%	<b>Total % Asbestos:</b> 5.0%
0230472-007 W26-8	Ceiling Popcorn Texture Popcorn Ceiling, White, Homogeneous, Fibrous	LAYER 1 100%	Other Non-Fibrous Material	95%	Chrysotile	5%
				<b>Total % Non-Asbestos:</b>	95.0%	<b>Total % Asbestos:</b> 5.0%



383 Industrial Way, Suite 300  
 Anchorage, AK 99501 (907) 258-8661  
 anchorage@oneatlas.com



Lab Code 200124-0

# PLM BULK SAMPLE ANALYSIS FOR ASBESTOS

Lab Login #:	0230472	Report #:	0230472
Atlas Job #:	NA	Report By:	A. Lang
Client Project #:	1	Report Date:	02/16/2023

Laboratory ID Sample No.	Sample Location Description	Layer No. Layer %	Non-Asbestos Components (%)	Asbestos Type (%)
-----------------------------	--------------------------------	----------------------	--------------------------------	----------------------

Analyzed by: <u></u> Amanda Lang Date: <u>02/16/2023</u> Date	Approved Signatory: <u></u> John Harness, Branch Manager Date: <u>02/16/2023</u> Date
---	--

Asbestos Containing Material (ACM) Definition: >1% asbestos by weight is considered an ACM.  
 TRACE = Less than 1% Asbestos by weight.  
 The Atlas Anchorage Laboratory is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP Lab Code: 200124-0) and in accordance with the recognized International Standard ISO/IEC 10725:2017. Analysis performed by: EPA-40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples or EPA Method 600/R-93/116: Method for the Determination of Asbestos in Bulk Building Materials at the discretion of the client or Atlas.

Unless a point-counting method is requested and noted for the sample, all quantities reported are based on calibrated visual estimation by Polarized Light Microscopy (PLM). Non-homogenous samples will be layered for testing unless stop-positive is requested by the client or otherwise stated in the chain of custody (COC). Asbestos results are reliable within 2 significant figures.

Analysis Report generated by Atlas relates only to items tested and submitted on the COC and must not be used by clients to claim product endorsement by the National Voluntary Laboratory Accreditation Program (NVLAP) or any agency of the U.S Government. This report shall not be reproduced, except in full, without written approval of the laboratory. Conditions of samples upon receipt were acceptable unless otherwise stated.

Liability Notice: Atlas and its personnel shall not be liable for any misinformation provided to us by the client regarding these samples.

Confidentiality Notice: The document(s) contained herein are confidential and privileged information, intended for the exclusive use of the individual or entity named above.

Laboratory Hours  
 Monday - Friday, 8:00 AM - 5:00 PM  
 Same Day TAT Cut-Off Time: 1:30 PM  
 After Hours Lab Opening Fee: \$200.00  
 Lab Emergency Contact: 907-258-8649



0230472

Atlas Anchorage Laboratory

## Form 102A ASBESTOS CHAIN OF CUSTODY

383 Industrial Way Suite 300 Anchorage, AK 99501 Phone: (907)258-8661 Email: [anchorage@oneatlas.com](mailto:anchorage@oneatlas.com)

<p align="center"><u>Project Information</u></p> <p>Project Name <u>West 26<sup>th</sup> Ave Apartments</u></p> <hr/> <p>Project No. <u>1</u> No. of Samples <u>7</u></p> <p>Inspector/Cert No. <u>John Pavitt, US EPA</u></p> <p>Collected By <u>John Pavitt</u> Date <u>2/14/23</u></p>	<p align="center"><u>TAT - Turnaround Time</u> (Business Days)</p> <p>Walk-In Client <input type="checkbox"/> SAME DAY <input checked="" type="checkbox"/> NEXT DAY <input type="checkbox"/> 5 DAY  <small>(For Customers who do not have an account with Atlas)</small></p> <p>Customer Account <input type="checkbox"/> SAME DAY <input type="checkbox"/> NEXT DAY <input type="checkbox"/> 5 DAY  <input type="checkbox"/> 2 DAY <input type="checkbox"/> 3 DAY</p> <p align="center"><u>Method of Payment</u></p> <p><input checked="" type="checkbox"/> INVOICE ACCOUNT <input type="checkbox"/> CREDIT CARD <input type="checkbox"/> CHECK</p>
<p align="center"><u>Client Information</u></p> <p>Atlas Client <u>US EPA</u></p> <p>Phone <u>(907) 271-3688</u></p> <p>Address <u>222 W. 7<sup>th</sup> Ave</u></p> <p>City <u>Anchorage</u> State <u>AK</u> Zip <u>99513</u></p>	<p align="center"><u>Report</u></p> <p>Contact Name <u>John Pavitt</u></p> <p>Phone Number <u>(907) 271-3688</u></p> <p>Email <u>pavitt.john@epagov</u></p> <p>*Verbal for RUSH TAT: Yes / No</p> <p>*Please Check for Stop Positive <input type="checkbox"/></p>

MATRIX:  PLM Asbestos Bulk (EPA 600/R-93/116)  PCM AIR (NIOSH 7400)  TEM AIR  Other: \_\_\_\_\_

HA	SAMPLE # (ID)	SAMPLE LOCATION/DESCRIPTION	VOLUME(L)	COLLECTION DATE
HA1	001	EXAMPLE (Office Wall) Northwest Corner	N/A	MM/DD/YYYY
	W26-1	Ceiling popcorn texture { { { { { {		2/14/2023
	W26-2			2/14/2023
	W26-3			2/14/2023
	W26-4			2/14/2023
	W26-5			2/14/2023
	W26-6			2/14/2023
	W26-8			2/14/2023

Comments:

Samples Relinquished By (Please Sign): John Pavitt Date: 2/15/23 Time: 11:15 (AM/PM)

**Lab Use Only**

Samples Received By: (Please Sign) [Signature] Date: 2/15/23 Time: 12:00 AM/PM

Lab Opening Fee \$200  Shipping Fee \$75  Courier Fee \$75  Other \_\_\_\_\_

\*Atlas May Reject Samples For One or More of the Following Reasons: Insufficient Material/Over-Large Sample Size, Unsafe Packaging, Missing Sample IDs and/or Volumes, Incomplete COC and Any Other Required Information.  
 \*Turnaround Times Are Not Always Guaranteed and Depend on Sample Volume and Lab Capacity.